

**From:** Davidson, Larry W

**Sent:** 11/23/2003 1:32 PM

**To:** Trapp, Paul W; Logan, Charles V; Yerrell, Scott K

**Cc:** Hawkins, Raymond A

**Bcc:**

**Attachments:**

**Subject:** ARU STEAM LEAKS

---

ARU

Okay,

It is cold weather again, and the ARU steam work is still lacking. We have a bad steam leak NE of 602-CD extractor (the same leak we had all last winter). We have a bad steam leak over the benzene reflux drum (the same leak we had last year), and who knows how many more leaks have developed during the course of the year. Mike and I were going to do something about the leak by the extractors, but the pipe is covered with asbestos insulation. I hope tarps will be spread Monday. Can we get some sort of repairs made on these steam lines in a hurry?

ISOM

Just a point of notice, I'm not going to jail by myself. I have been trying to get an 1 1/2" hose for the discharge of the diaphragm pump for the ISOM west DWS for over a year and a half. The pump has been moved to accommodate Title V, but the hose on the pump has 3 holes in it, and the DWS has oil in it. Are we going to have to run hard pipe ourselves?

NDU

Operators want to know why we can't get F-0165 fixed so it will control. It has blocks and by-passes. They say it has been a problem since the unit came up.